

FITNESS CERTIFICATE

To be filled by Inspecting Officer (Assistant Engineer)
(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

- 1 Name of Officer : ANIL KUMAR A P
 2 Name of School : CONCORD PUBLIC SCHOOL , MUTTANNUR
 3 Location : PATTANUR ,670595. Mattnnur Sub Dt.Thalasseri Edn. Dt
 4 Period for which the certificate is issued : Up to 31st March 2023
 5 Types of building : Permanent RCCFramed

G.F.	
1)	7.00 X 6.00 x 3.60 m (3-Room)
F.F.	
2)	7.00X 9.00 x 3.60 m (3-Room)
S.F.	
3)	7.00 X 9.00 x 3.60 m (3-Room)

6 Nature of defect if any

- a) Foundation and Basement : Nil
 b) Superstructure : Nil
 c) Doors and Windows : Nil
 d) Wood work wrought and put up : Nil
 e) Roof : Nil
 f) Flooring : Nil
 g) Miscellaneous(Cracks if any) : Nil

7 Any Major defects noticed which will render the building unsafe in any manner : No

8 Whether maintenance work have been done properly : Yes

9 whether the structure is sound or not for conducting classes : Yes, The structure is safe for conducting classes under normal wind and weather condition

Note: 1 The stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood etc.
 2 Any additional observation deemed necessary for the certificate may be furnished separately with the certificate

Certified that the School was inspected by me on 25.05.2022 And found to be fit/unfit to conduct classes for the period for the reasons stated above.

Place: Kololam

Date: 25-05-2022



Signature
ANIL KUMAR A.P
 (PEN: 399888)
 Assistant Engineer
 LSGD (LID & EW) Section
 Koodali Grama Panchayat
 Kololam, P.O. Edayannur-670595

FITNESS CERTIFICATE

To be filled by Inspecting Officer (Assistant Engineer)
(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

- 1 Name of Officer : ANIL KUMAR A P
 2 Name of School : CONCORD PUBLIC SCHOOL , MUTTANNUR
 3 Location : Pattanur ,670595. Mattnnur Sub Dt.Thalasseri Edn. Dt
 4 Period for which the certificate is issued : Up to 31st March 2023
 5 Types of building : Permanent ,Tiled roof

G.F.	
1)	7.00 X 5.00 x 3.60 m (Staff Room) Tiled Roof
2)	6.00 x 5.00x 3.60 m (office Room)
3)	13.00x 7.00x 3.65 m (Admin. block)
4)	6.10x 7.00x 3.65 m (3- No Class Room)
5)	6.10x 7.00x 3.65 m (3-No Class Room)

6 Nature of defect if any

- a) Foundation and Basement : Nil
 b) Superstructure : Nil
 c) Doors and Windows : Nil
 d) Wood work wrought and put up : Nil
 e) Roof : Nil
 f) Flooring : Nil
 g) Miscellaneous(Cracks if any) : Nil

7 Any Major defects noticed which will render the building unsafe in any manner : No

8 Whether maintenance work have been done properly : Yes

9 whether the structure is sound or not for conducting classes : Yes, The structure is safe for conducting classes under normal wind and weather condition

Note: 1 The stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood etc.
 2 Any additional observation deemed necessary for the certificate may be furnished separately with the certificate

Certified that the School was inspected by me on 25/5/22 And found to be fit/unfit to conduct classes for the period for the reasons stated above.

Place: Kololam

Date: 25/5/22



Signature
ANIL KUMAR A.P
 (PEN: 399888)
 Assistant Engineer
 LSGD (LID & EW) Section
 Koodali Grama Panchayat
 Kololam, P.O. Edayannur-670595